

TO FIT SIZE CHART

*Measurements refer to body size, not garment dimensions



R321X - TECHNICAL TROUSER

25.02.2016

| | XS | S | M | L | XL | 2XL | 3XL | 4XL | 5XL |
|----------------------|----|----|----|----|----|-----|-----|-----|-----|
| Waist in inches* | 30 | 32 | 34 | 36 | 38 | 40 | 42 | 44 | 46 |
| Waist in cm* | 76 | 84 | 86 | 91 | 96 | 102 | 107 | 112 | 117 |
| German clothing size | 46 | 48 | 50 | 52 | 54 | 56 | 58 | 60 | 62 |

HOW TO MEASURE CHEST: Place the tape measure across the back, underneath the arms and then across the fullest part of the chest.

1 Inch = 2,54 cm